

Basevan.com General Inspection

Inspection details

| Name of inspector | Wallis |
|--------------------|------------|
| Date of inspection | 24/10/2024 |
| Signature | E. WA |

Vehicle details

| VCITIOIC UCIAIIS | |
|------------------------------------|-------------------|
| Vehicle registration | WJ19ZTR |
| Vehicle chassis no. | ZFA25000002J91990 |
| Miles (if in km, multiply by 0.62) | 246445 |
| Make | Fiat |
| Model | Ducato |
| Transmission | Manual, 6 speed |
| Factory immobiliser installed | Yes |
| Speed limiter installed | N/A |
| Drive configuration | FWD |
| Gross Vehicle Weight (kg) | 4250 |
| Towing capacity | 2250 |
| Tow bar installed | No |


Off side front

| Age (month/year) Manufactured | 05/24 |
|-------------------------------|--------------|
| Make, brand. | Michelin |
| Tyre size | 225/75/R16 |
| Pressure 1 | 65 |
| Pressure 2 | |
| Wearing / Perishing (inner) | Replace soon |
| Wearing / Perishing (outer) | Replace soon |
| tread depth (mm) | 3 |
| General comments | |



Basevan.com General Inspection

Images of tyre



Near side front

| Age (month/year) Manufactured | 21/23 |
|-------------------------------|------------|
| Make, brand. | Michelin |
| Tyre size | 225/75/R16 |
| Pressure 1 | 64 |
| Pressure 2 | |
| Wearing / Perishing (inner) | Medium |
| Wearing / Perishing (outer) | Medium |
| tread depth (mm) | 4 |
| General comments | |



Basevan.com General Inspection

Images of tyre




near side rear

| Age (month/year) Manufactured | 36/23 |
|-------------------------------|------------|
| Make, brand. | Michelin |
| Tyre size | 225/75/R16 |
| Pressure 1 | 68 |
| Pressure 2 | |
| Wearing / Perishing (inner) | none |
| Wearing / Perishing (outer) | None |
| tread depth (mm) | 8 |
| General comments | |



Basevan.com General Inspection

Images of tyre



Off side rear

| Age (month/year) Manufactured | 36/23 |
|-------------------------------|------------|
| Make, brand. | Michelin |
| Tyre size | 225/75/R16 |
| Pressure 1 | 71 |
| Pressure 2 | |
| Wearing / Perishing (inner) | Slight |
| Wearing / Perishing (outer) | Slight |
| tread depth (mm) | 6 |
| General comments | |



Basevan.com General Inspection

Images of tyre



off side Inner (for twin wheel vans)

| Is the vehicle a twin wheel axle? (if no don't fill out) | No |
|--|----|
| Age (month/year) Manufactured | |
| Make, brand. | |
| Tyre size | |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | |
| Wearing / Perishing (outer) | |

Powered by *** fastfield**



Basevan.com General Inspection

| tread depth (mm) | |
|------------------|--|
| General comments | |
| Images of tyre | |

near side Inner (for twin wheel vans)

| TICAL SIAC HITCH (TOT WITH W | |
|--|----|
| Is the vehicle a twin wheel axle? (if no don't fill out) | No |
| Age (month/year) Manufactured | |
| Make, brand. | |
| Tyre size | |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | |
| Wearing / Perishing (outer) | |
| tread depth (mm) | |
| General comments | |
| Images of tyre | |

Spare wheel

| Spare writer | |
|--|----|
| Spare installed? (If no, don't fill out) | No |
| Age (month/year) Manufactured | |
| Make, brand. | |
| Tyre size | |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | |
| Wearing / Perishing (outer) | |
| tread depth (mm) | |
| General comments | |
| Images of tyre | |

Vehicle locking

| Factory central locking fitted? | Yes |
|--|-----|
| Response from key fob? | Yes |
| Response from in-cab locking button? | |
| Do all the doors lock from central locking function? | All |



Basevan.com General Inspection

| Select the following doors that lock. | N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear |
|--|--|
| Method of locking | Fob |
| In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at pints safely? | Yes |

How many keys present at time of inspection?



In cab checks

Comment

| Number of seats (cab only) | Driver & 1 passenger |
|----------------------------|----------------------|
| Cab heater check | Does not work |
| Comment on cab heater | |



Basevan.com General Inspection

| Electric windows present | Yes |
|---|---|
| Cab windows function check | Driver side function, Passenger side function |
| Air conditioning present | Yes |
| Charging socket present (cigarette lighter) | Yes |
| Function working? | Yes |
| Radio / Media system fitted? | Yes |
| Radio / media system check | Functions |
| Reverse camera present? | Yes |
| Reverse camera functioning? | Yes |
| Show any damage or missing items | |

General mechanical checks

| Fuel level | 1/2 Full |
|-----------------------------------|---------------------------|
| Oil level | Full |
| Oil conditon | Clean |
| Start up, chassis battery check | Started without jump pack |
| Start-up from cold | 2 seconds |
| Exhaust smoke from cold | Normal |
| Output Voltage of Alternator test | 14.1 |
| Chain or Belt driven engine? | Belt |
| If belt any proof of change? | N/A |
| Coolant condition | Dirty |
| Coolant level | Low |
| Anti-freeze temperature check | |
| Washer fluid | Medium |
| Brake fluid | Full |
| Power steering fluid | Maximum |
| Dashboard warning light | No warning lights |




Basevan.com General Inspection

OBD Scan results ď System search finished, no error codes found

Powered by 🍫 fastfield Page 9 of 10



Basevan.com General Inspection



Powered by *** fastfield**