

Basevan.com General Inspection

Inspection details

| Name of inspector | Franklyn T Bromfield |
|--------------------|----------------------|
| Date of inspection | 16/12/2024 |
| Signature | FUZ |

Vehicle details

| verilde details | |
|------------------------------------|-------------------|
| Vehicle registration | LJ15LJZ |
| Vehicle chassis no. | WOLMTF8ZWFB069957 |
| Miles (if in km, multiply by 0.62) | 66345 |
| Make | Vauxhall |
| Model | Movano |
| Transmission | Manual, 6 speed |
| Factory immobiliser installed | Yes |
| Speed limiter installed | |
| Drive configuration | RWD |
| Gross Vehicle Weight (kg) | 4500 |
| Towing capacity | 3000 |
| Tow bar installed | No |

Off side front

| Age (month/year) Manufactured | 25/21 |
|-------------------------------|------------|
| Make, brand. | Good Year |
| Tyre size | 195/75/R16 |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | none |
| Wearing / Perishing (outer) | None |
| tread depth (mm) | 5 |
| General comments | good tyre |



Basevan.com General Inspection

Images of tyre




Near side front

| Age (month/year) Manufactured | 25/21 |
|-------------------------------|------------|
| | |
| Make, brand. | Good Year |
| Tyre size | 195/75/R16 |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | none |
| Wearing / Perishing (outer) | None |
| tread depth (mm) | 5 |
| General comments | good tyre |



Basevan.com General Inspection

Images of tyre



near side rear

| Age (month/year) Manufactured | 21/19 |
|-------------------------------|-----------------|
| Make, brand. | Good Year |
| Tyre size | 195/75/R16 |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | none |
| Wearing / Perishing (outer) | None |
| tread depth (mm) | 7 |
| General comments | great condition |



Basevan.com General Inspection

Images of tyre




Off side rear

| Age (month/year) Manufactured | 21/19 |
|-------------------------------|------------|
| Make, brand. | Good Year |
| Tyre size | 195/75/R16 |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | none |
| Wearing / Perishing (outer) | None |
| tread depth (mm) | 7 |
| General comments | great tyre |



Basevan.com General Inspection

Images of tyre



off side Inner (for twin wheel vans)

| | 331 73.137 |
|--|------------|
| Is the vehicle a twin wheel axle? (if no don't fill out) | N/A |
| Age (month/year) Manufactured | 21/19 |
| Make, brand. | Good Year |
| Tyre size | 195/75/R16 |
| Pressure 1 | |
| Pressure 2 | |
| Wearing / Perishing (inner) | none |
| Wearing / Perishing (outer) | None |



Basevan.com General Inspection

| tread depth (mm) | 7 |
|------------------|---|
| General comments | good tyre |
| | THE RESIDENCE OF THE PROPERTY |

Images of tyre



near side Inner (for twin wheel vans)

| Is the vehicle a twin wheel axle? (if no don't fill out) | Yes |
|--|------------|
| Age (month/year) Manufactured | 21/19 |
| Make, brand. | Good Year |
| Tyre size | 195/75/R16 |
| Pressure 1 | |
| Pressure 2 | |



Basevan.com General Inspection

| Wearing / Perishing (inner) | none |
|-----------------------------|------------|
| Wearing / Perishing (outer) | None |
| tread depth (mm) | 6 |
| General comments | great tyre |

Images of tyre



Spare wheel

| Spare installed? (If no, don't fill out) | No |
|--|----|
| Age (month/year) Manufactured | |
| Make, brand. | |
| Tyre size | |



Basevan.com General Inspection

| Pressure 1 | |
|-----------------------------|--|
| Pressure 2 | |
| Wearing / Perishing (inner) | |
| Wearing / Perishing (outer) | |
| tread depth (mm) | |
| General comments | |
| Images of tyre | |

Vehicle locking

| T OT HOLD TO OTALLING | |
|--|--|
| Factory central locking fitted? | Yes |
| Response from key fob? | Yes |
| Response from in-cab locking button? | Yes |
| Do all the doors lock from central locking function? | All |
| Select the following doors that lock. | N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear |
| Method of locking | Fob |
| In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely? | Yes |

Powered by *** fastfield**



Basevan.com General Inspection

How many keys present at time of inspection?



Comment

In cab checks

| Number of seats (cab only) | Driver & 1 passenger |
|---|---|
| Cab heater check | Works on all settings |
| Comment on cab heater | dial a little notchy |
| Electric windows present | Yes |
| Cab windows function check | Driver side function, Passenger side function |
| Air conditioning present | Yes |
| Charging socket present (cigarette lighter) | Yes |



Basevan.com General Inspection

| Function working? | Yes |
|------------------------------|--|
| Radio / Media system fitted? | |
| Radio / media system check | Functions |
| Reverse camera present? | No |
| Reverse camera functioning? | N/A |
| | The state of the s |

Show any damage or missing items



General mechanical checks

| Contrat modifications | |
|---------------------------------|---------------------------|
| Fuel level | 1/2 Full |
| Oil level | Full |
| Oil conditon | Clean |
| Start up, chassis battery check | Started without jump pack |


Powered by 🍫 fastfield Page 10 of 11



Basevan.com General Inspection

| Start-up from cold | Instant |
|-----------------------------------|-------------------|
| Exhaust smoke from cold | Normal |
| Output Voltage of Alternator test | 13.7 |
| Chain or Belt driven engine? | Chain |
| If belt any proof of change? | n/a |
| Coolant condition | Clean |
| Coolant level | Full |
| Anti-freeze temperature check | -15 |
| Washer fluid | Medium |
| Brake fluid | Full |
| Power steering fluid | Maximum |
| Dashboard warning light | No warning lights |
| OBD Scan results | |

Engine bay photo



Comment mechanically very good, normal for a movano :)

Powered by 🍫 fastfield Page 11 of 11