



Basevan.com General Inspection

Inspection details

Name of inspector	Franklyn T Bromfield
Date of inspection	20/01/2025
Signature	

Vehicle details

Vehicle registration	MX05 GXU
Vehicle chassis no.	ZCFC297100D267680
Miles (if in km, multiply by 0.62)	26957mi
Make	Iveco
Model	Daily
Transmission	Manual, 5 speed
Factory immobiliser installed	Yes
Speed limiter installed	No
Drive configuration	RWD
Gross Vehicle Weight (kg)	3200
Towing capacity	2800kg
Tow bar installed	No

Off side front

Age (month/year) Manufactured	18:19
Make, brand.	Dunlop
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	205/70/15- great tyre



Basevan.com General Inspection

Images of tyre



Near side front

Age (month/year) Manufactured	18:19
Make, brand.	Dunlop
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	205/70/15- great tyre



Basevan.com General Inspection

Images of tyre



near side rear

Age (month/year) Manufactured	18/19
Make, brand.	Dunlop
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	205/70/15- great tyre



Basevan.com General Inspection

Images of tyre



Off side rear

Age (month/year) Manufactured	18/19
Make, brand.	Dunlop
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	205/70/15- great tyre



Basevan.com General Inspection

Images of tyre



off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	



Basevan.com General Inspection

tread depth (mm)	
General comments	
Images of tyre	

near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Spare wheel


Spare installed? (If no, don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Vehicle locking

Factory central locking fitted?	No
Response from key fob?	N/A
Response from in-cab locking button?	N/A
Do all the doors lock from central locking function?	None



Basevan.com General Inspection

Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Key
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	works as intended

In cab checks

Number of seats (cab only)	Driver & 2 passenger
Cab heater check	Works on all settings
Comment on cab heater	functions as should



Basevan.com General Inspection

Electric windows present	No
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	No
Charging socket present (cigarette lighter)	Yes
Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Not functioning
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

General mechanical checks

Fuel level	1/2 Full
Oil level	Medium
Oil conditon	Clean
Start up, chassis battery check	Started, but required boost pack, Chassis battery requires charging
Start-up from cold	Instant
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	13.6
Chain or Belt driven engine?	Belt
If belt any proof of change?	n/a
Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	-15
Washer fluid	Full
Brake fluid	Full
Power steering fluid	Maximum
Dashboard warning light	No warning lights
OBD Scan results	




Basevan.com General Inspection

Engine bay photo





Basevan.com General Inspection

	
Comment	mechanically great, nice mileage!