




BaseVan Initial Inspection

Inspection details

Name of inspector	Franklyn T Bromfield
Date of inspection	19/09/2024
Signature	

Vehicle details


Vehicle registration	WX05XXB
Vehicle chassis no.	WDB9046122R741637
Miles (if in km, multiply by 0.62)	122,140
Make	Mercedes
Model	Sprinter
Transmission	Manual, 5 speed
Factory immobiliser installed	Yes
Speed limiter installed	Yes
Drive configuration	
Gross vehicle weight	4600kg
Towing capacity	2000
Tow bar installed	No

Off side front

Age (month/year) Manufactured	15/14
Make, brand.	Good Year
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	6
General comments	195/70R15c



BaseVan Initial Inspection



Near side front

Age (month/year) Manufactured	34/20
Make, brand.	Budget
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	185/65R15



BaseVan Initial Inspection

Images of tyre



near side rear

Age (month/year) Manufactured	22/15
Make, brand.	Continental
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	6
General comments	185/65R15



BaseVan Initial Inspection

Images of tyre




Off side rear

Age (month/year) Manufactured	22/15
Make, brand.	Continental
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	6
General comments	185/65R15



BaseVan Initial Inspection



off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	
Make, brand.	Continental
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight



BaseVan Initial Inspection


tread depth (mm)	
General comments	185/65R15
Images of tyre	

near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	13/19
Make, brand.	Continental
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	



BaseVan Initial Inspection

Wearing / Perishing (inner)	Medium
Wearing / Perishing (outer)	Medium
tread depth (mm)	5
General comments	185/65R15
Images of tyre	

Spare wheel

Spare installed? (If no, don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	



BaseVan Initial Inspection

Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Vehicle locking

Factory central locking fitted?	No
Response from key fob?	N/A
Response from in-cab locking button?	N/A
Do all the doors lock from central locking function?	None
Select the following doors that lock.	N/S Front
Method of locking	Key
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	No



BaseVan Initial Inspection

How many keys present at time of inspection?



Comment Only has n/s front and rear doors

In cab checks

Number of seats (cab only)	Driver only
Cab heater check	Works on all settings
Comment on cab heater	
Electric windows present	No
Cab windows function check	Driver side function
Air conditioning present	No
Charging socket present (cigarette lighter)	Yes



BaseVan Initial Inspection

Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Requires code
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

General mechanical checks

Fuel level	1/2 Full
Oil level	Medium
Oil conditon	Clean
Start up, chassis battery check	Started without jump pack
Start-up from cold	2 seconds
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	13.9
Chain or Belt driven engine?	Chain
If belt any proof of change?	
Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	
Washer fluid	Full
Brake fluid	Full
Power steering fluid	Miniumum
Dashboard warning light	No warning lights
OBD Scan results	



BaseVan Initial Inspection

<p>Engine bay photo</p>	
<p>Comment</p>	