




Basevan.com General Inspection

Inspection details

Name of inspector	Franklyn T Bromfield
Date of inspection	04/04/2025
Signature	

Vehicle details

Vehicle registration	LK08CPY
Vehicle chassis no.	WDB6683222N126652
Miles (if in km, multiply by 0.62)	122,238mi (197159km)
Make	Mercedes-Benz
Model	Vario
Transmission	Automatic
Factory immobiliser installed	Yes
Speed limiter installed	Yes
Drive configuration	RWD
Gross Vehicle Weight (kg)	5990
Towing capacity	3000kg
Tow bar installed	No

Off side front

Age (month/year) Manufactured	19/20
Make, brand.	Budget
Tyre size	215/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	Nice tyre



Basevan.com General Inspection

Images of tyre





Basevan.com General Inspection



Near side front

Age (month/year) Manufactured	19/20
Make, brand.	Budget
Tyre size	215/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	nice tyre



Basevan.com General Inspection

Images of tyre





Basevan.com General Inspection



near side rear

Age (month/year) Manufactured	51/19
Make, brand.	GT Radial
Tyre size	215/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	very good tyre



Basevan.com General Inspection

Images of tyre





Basevan.com General Inspection



Off side rear

Age (month/year) Manufactured	11/21
Make, brand.	Cooper
Tyre size	215/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	slight perishing inner, good tread



Basevan.com General Inspection

Images of tyre





Basevan.com General Inspection




off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	11/21
Make, brand.	Cooper
Tyre size	215/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None



Basevan.com General Inspection


tread depth (mm)	8
General comments	good tyre
Images of tyre	

near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	51/19
Make, brand.	GT Radial
Tyre size	215/75/R16
Pressure 1	
Pressure 2	



Basevan.com General Inspection


Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	good tyre, nice tread
Images of tyre	

Spare wheel

Spare installed? (If no, don't fill out)	Yes
Age (month/year) Manufactured	21/17
Make, brand.	Budget
Tyre size	215/75/R16



Basevan.com General Inspection

Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	10
General comments	Never used
Images of tyre	



Basevan.com General Inspection




Vehicle locking

Factory central locking fitted?	No
Response from key fob?	N/A
Response from in-cab locking button?	N/A
Do all the doors lock from central locking function?	None
Select the following doors that lock.	N/S Front, O/S Front
Method of locking	Key



Basevan.com General Inspection

In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	6 keys wow, all works good

In cab checks

Number of seats (cab only)	Driver & 2 passenger
Cab heater check	Works on all settings
Comment on cab heater	functions well
Electric windows present	No
Cab windows function check	Driver side function, Passenger side function



Basevan.com General Inspection

Air conditioning present	No
Charging socket present (cigarette lighter)	Yes
Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

General mechanical checks

Fuel level	1/2 Full
Oil level	Full
Oil conditon	Clean
Start up, chassis battery check	Started, but required boost pack, Chassis battery requires charging
Start-up from cold	Instant
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	
Chain or Belt driven engine?	Chain
If belt any proof of change?	n/a
Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	-23
Washer fluid	Medium
Brake fluid	Full
Power steering fluid	Maximum
Dashboard warning light	No warning lights
OBD Scan results	



Basevan.com General Inspection

Engine bay photo





Basevan.com General Inspection



Comment

incredible