




## Basevan.com General Inspection

### Inspection details

Name of inspector	Rupert Beeston
Date of inspection	04/01/2025
Signature	

### Vehicle details

Vehicle registration	ASZ3755
Vehicle chassis no.	VF3YCTMFC12A85456
Miles (if in km, multiply by 0.62)	43638
Make	PEUGUEOT
Model	BOXER
Transmission	6 speed, Manual
Factory immobiliser installed	Yes
Speed limiter installed	No
Drive configuration	FWD
Gross Vehicle Weight (kg)	3500
Towing capacity	2500
Tow bar installed	No

### Off side front

Age (month/year) Manufactured	21/12
Make, brand.	Other (comment)
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	Slight
tread depth (mm)	2
General comments	Bridgestone tyre, 225/70/R15, i would replace before next MOT.



## Basevan.com General Inspection

Images of tyre



### Near side front

Age (month/year) Manufactured	21/12
Make, brand.	
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	Slight
tread depth (mm)	2
General comments	Bridgestone, I'd also replace at next MOT



## Basevan.com General Inspection

Images of tyre



### near side rear

Age (month/year) Manufactured	43/22
Make, brand.	Good Year
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	Tyre is like new.





## Basevan.com General Inspection

Images of tyre



### Off side rear

Age (month/year) Manufactured	15/22
Make, brand.	Good Year
Tyre size	Not here (see comment)
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	Like new!



## Basevan.com General Inspection

Images of tyre



### off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	



## Basevan.com General Inspection

tread depth (mm)	
General comments	
Images of tyre	

### near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

### Spare wheel


Spare installed? (If no, don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

### Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes
Response from in-cab locking button?	Yes
Do all the doors lock from central locking function?	All



## Basevan.com General Inspection

Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Key, Fob
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	Only 1 key present


### In cab checks

Number of seats (cab only)	Driver & 1 passenger
Cab heater check	Works on all settings
Comment on cab heater	All working fine





## Basevan.com General Inspection

Electric windows present	Yes
Cab windows function check	Passenger side function, Driver side function
Air conditioning present	No
Charging socket present (cigarette lighter)	Yes
Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	





## Basevan.com General Inspection





## Basevan.com General Inspection



### General mechanical checks

Fuel level	Full
Oil level	
Oil conditon	Serviced by Basevan
Start up, chassis battery check	Started without jump pack, Chassis battery new
Start-up from cold	Instant
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	13.8
Chain or Belt driven engine?	Chain
If belt any proof of change?	



## Basevan.com General Inspection


Coolant condition	Clean
Coolant level	Full
Anti-freeze temperature check	-15
Washer fluid	Medium, And now topped up to correct level
Brake fluid	Medium
Power steering fluid	Maximum
Dashboard warning light	
OBD Scan results	







## Basevan.com General Inspection





## Basevan.com General Inspection



Comment

No Adblue present on vehicle