




Basevan.com General Inspection

Inspection details

Name of inspector	Wallis
Date of inspection	07/01/2025
Signature	

Vehicle details

Vehicle registration	YJ55LSY
Vehicle chassis no.	WDB903662R866287
Miles (if in km, multiply by 0.62)	95779
Make	Mercedes
Model	Sprinter
Transmission	Manual, 5 speed
Factory immobiliser installed	Yes
Speed limiter installed	N/A
Drive configuration	RWD
Gross Vehicle Weight (kg)	3500
Towing capacity	2800
Tow bar installed	No

Off side front

Age (month/year) Manufactured	28/15
Make, brand.	Michelin
Tyre size	Not here (see comment)
Pressure 1	50
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	6
General comments	225/70R15C



Basevan.com General Inspection

Images of tyre



Near side front

Age (month/year) Manufactured	28/15
Make, brand.	Michelin
Tyre size	Not here (see comment)
Pressure 1	44
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	7
General comments	225/70R15C



Basevan.com General Inspection

Images of tyre



near side rear

Age (month/year) Manufactured	36/20
Make, brand.	Michelin
Tyre size	Not here (see comment)
Pressure 1	58
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	225/70R15C



Basevan.com General Inspection

Images of tyre



Off side rear

Age (month/year) Manufactured	09/21
Make, brand.	Michelin
Tyre size	Not here (see comment)
Pressure 1	60
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	



Basevan.com General Inspection

Images of tyre



off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	



Basevan.com General Inspection

tread depth (mm)	
General comments	
Images of tyre	

near side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Spare wheel


Spare installed? (If no, don't fill out)	No
Age (month/year) Manufactured	
Make, brand.	
Tyre size	
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	
Wearing / Perishing (outer)	
tread depth (mm)	
General comments	
Images of tyre	

Vehicle locking

Factory central locking fitted?	No
Response from key fob?	N/A
Response from in-cab locking button?	N/A
Do all the doors lock from central locking function?	None



Basevan.com General Inspection

Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Key
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	

In cab checks

Number of seats (cab only)	Driver & 1 passenger
Cab heater check	Works only on max
Comment on cab heater	



Basevan.com General Inspection



Electric windows present	No
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	No
Charging socket present (cigarette lighter)	Yes
Function working?	Yes
Radio / Media system fitted?	Yes
Radio / media system check	Functions
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

General mechanical checks

Fuel level	1/2 Full
Oil level	Full
Oil condition	Clean
Start up, chassis battery check	Started, but required boost pack
Start-up from cold	3 seconds
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	14
Chain or Belt driven engine?	Chain
If belt any proof of change?	N/A
Coolant condition	Clean
Coolant level	Low
Anti-freeze temperature check	
Washer fluid	Full
Brake fluid	Full
Power steering fluid	Minimum
Dashboard warning light	EML present



Basevan.com General Inspection

<p>OBD Scan results</p>	 <p>DTCs (8)</p> <ul style="list-style-type: none">P1630 - Engine Immobiliser authorisationP2007 - Fuel delivery pressure monitoringP2203 - Externa quantity control by ESP control moduleP0500 - Vehicle speed signalP1470 - Boost pressure regulation
<p>Engine bay photo</p>	
<p>Comment</p>	