




BaseVan Initial Inspection

Inspection details

Name of inspector	Franklyn T Bromfield
Date of inspection	18/09/2024
Signature	

Vehicle details

Vehicle registration	CN64FEJ
Vehicle chassis no.	WOLMTF8VHEB056138
Miles (if in km, multiply by 0.62)	94683
Make	Vauxhall
Model	Movano
Transmission	Manual, 6 speed
Factory immobiliser installed	Yes
Speed limiter installed	N/A
Drive configuration	RWD
Gross vehicle weight	4600kg
Towing capacity	3000
Tow bar installed	No

Off side front

Age (month/year) Manufactured	22/22
Make, brand.	Good Year
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Medium
Wearing / Perishing (outer)	Medium
tread depth (mm)	5
General comments	



BaseVan Initial Inspection

Images of tyre




Near side front

Age (month/year) Manufactured	24/22
Make, brand.	Good Year
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	Slight
Wearing / Perishing (outer)	Slight
tread depth (mm)	6
General comments	



BaseVan Initial Inspection



near side rear

Age (month/year) Manufactured	
Make, brand.	Good Year
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	



BaseVan Initial Inspection

Images of tyre




Off side rear

Age (month/year) Manufactured	19/23
Make, brand.	Good Year
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	8
General comments	



BaseVan Initial Inspection

Images of tyre




off side Inner (for twin wheel vans)

Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	24/22
Make, brand.	Good Year
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None



BaseVan Initial Inspection

tread depth (mm)	7
General comments	
Images of tyre	

near side Inner (for twin wheel vans)


Is the vehicle a twin wheel axle? (if no don't fill out)	Yes
Age (month/year) Manufactured	23/22
Make, brand.	Good Year
Tyre size	195/75/R16
Pressure 1	
Pressure 2	



BaseVan Initial Inspection

Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	7
General comments	
Images of tyre	

Spare wheel


Spare installed? (If no, don't fill out)	Yes
Age (month/year) Manufactured	27/18
Make, brand.	Good Year
Tyre size	195/75/R16
Pressure 1	
Pressure 2	
Wearing / Perishing (inner)	none
Wearing / Perishing (outer)	None
tread depth (mm)	9
General comments	
Images of tyre	

Vehicle locking

Factory central locking fitted?	Yes
Response from key fob?	Yes




BaseVan Initial Inspection

Response from in-cab locking button?	
Do all the doors lock from central locking function?	All
Select the following doors that lock.	N/S Front, O/S Front, N/S SL, N/S Rear, O/S Rear
Method of locking	Fob, Key
In conclusion can all the doors be locked in some way and thus the vehicle can be left unattended at night safely?	Yes
How many keys present at time of inspection?	
Comment	

In cab checks



BaseVan Initial Inspection


Number of seats (cab only)	Driver & 2 passenger
Cab heater check	Works on all settings
Comment on cab heater	
Electric windows present	Yes
Cab windows function check	Driver side function, Passenger side function
Air conditioning present	Yes
Charging socket present (cigarette lighter)	Yes
Function working?	Yes
Radio / Media system fitted?	No
Radio / media system check	N/A not installed
Reverse camera present?	No
Reverse camera functioning?	N/A
Show any damage or missing items	

General mechanical checks

Fuel level	1/2 Full
Oil level	Full
Oil conditon	Requires replacing
Start up, chassis battery check	Started without jump pack
Start-up from cold	2 seconds
Exhaust smoke from cold	Normal
Output Voltage of Alternator test	



BaseVan Initial Inspection

Chain or Belt driven engine?	Chain
If belt any proof of change?	
Coolant condition	Clean
Coolant level	Medium
Anti-freeze temperature check	
Washer fluid	Medium
Brake fluid	Full
Power steering fluid	Maximum
Dashboard warning light	Service light
OBD Scan results	
Engine bay photo	
Comment	